吉本産業株式会社

INSTRUCTION MANUAL US01-2301

ULTRA SURFACE COUNTER

cause scratches on the surface.

Thank you for your purchase of our product. We kindly ask you to carefully read this instruction manual to ensure the correct and safe use of the product. Please keep this manual in a secure place for future reference.

SAFETY PRECAUTIONS (must be adhered to)

Carefully review this "Safety Precautions" section before using the product to ensure proper usage. Failure to study these precautions can lead to serious consequences, including injuries or property damage.



CAUTION

⚠

Do not run around the counter. ⚠ There is a risk of injury from Caution crashing with corners of the counter.



For the electrical appliances, stoves, sinks, etc., that are incorporated, please adhere to the manual instructions and the information displayed on the products themselves. Improper installation can lead to unexpected accidents or malfunctions.







rectly, as this may cause discoloration

and deformation.

% Please confirm color and appearance with the actual sample.

Please confirm color and app	pearance with the actual samp	le.	
C101	C301	C303	
C150	C200	C201	
C202	C400	C410	
CAN1000	CAN1100	CAN1200	6

■ Care instructions

To maintain the beauty of the surface, diligent care is important.

2 steps of care

①Wipe with water

②Wipe dry





Level of dirt or scratches	Maintenance method
[Daily basis]	 Wipe thoroughly with damp cloth. Wipe dry with soft cloth. Note : If stains are left long, they become sticky and hard to remove. Please take good care of the product.
[Stubborn stains]	 Please follow the steps below. If the stain cannot be removed at each step, proceed to the next step. 1. Apply neutral detergent (for kitchen use) to a soft cloth or sponge and wipe away the dirt. 2. Place a cloth, such as gauze, soaked in neutral detergent on the stained area for a while (about 5 minutes), then wipe it off. 3. Wipe with a chlorine-based bleach, such as kitchen bleach. 4. Place a cloth, such as gauze, soaked in chlorine-based bleach, such as kitchen bleach, on the stained area for a while (about 5 minutes), then wipe it off. 5. If the stain persists, repeat step 4. Note: Always rinse with water at the end to completely remove the detergent, and wipe with a dry cloth.



■ Cleaning tools

Can be used.

S Cannot be used. Scrubbing may scratch the surface.

Soft cloth (such as cloth for wiping glasses)	Urethane sponge (sponge part)	Net sponge	Nylon dish scrubber (no abrasive particles)	Kitchen scrubber with abrasive particles	Melamine sponge	Stainless steel scrubber
	<i></i>					
O	Ø	Ø	Ø	۲	۲	۵

Detergent

O Can be used.

S Can not be used. When detergent containing abrasives dries, white marks may adhere to the surface and may not come off. Please wipe with water immediately.

%Hardness increases from left to right

Liquid detergent	Kitchen detergent	Household detergent	Cream cleanser	Powder cleanser
Weak acidic ~ weak alkaline	Weak alkaline	Neutral ~ Weak alkaline	Weak alkaline	Weak alkaline
Remove stains	Remove oil stains, hard water stain, disinfection, deodorization	Remove oil stains, disinfection	Remove sticky stains, oil stains, hard water stain	Remove stubborn stains, oil stains
For stains remov- able with water. Weak acidity pre- vent fingerprints. Always wipe with water.	For stains removeble with water. Always wipe with water.	Can be used for daily cleaning of any place in households.	The fine particles remove stains and grime.	Stronger abrasive power than cream cleansers. Removes stains with rough par- ticles.
Ø	0	Ø	8	8

s	2		

Level of dirt or scratches	Maintenance method		
[Oily stains]	 Please follow the steps below. If the stain cannot be removed at each step, proceed to the next step. 1. Wipe with solvents such as alcohol, thinner, or benzene. 2. Place a cloth, such as gauze, soaked in the solvent on the stained area for a while (about 5 minutes), then wipe it off. 3. Wipe with chlorine-based bleach, such as kitchen bleach. 4. Place a cloth, such as gauze, soaked in chlorine-based bleach, such as kitchen bleach, on the stained area for a while (about 5 minutes), then wipe it off. 5. If the stain persists, repeat step 4. Note: Always rinse with water at the end to completely remove the detergent, and wipe with a dry cloth. 		
[Minor scratches]	 Clean the scratched area and its surroundings with neutral detergent to remove dirt. Rinse the cleaned area with water to completely remove the detergent. Ensure thorough drying as leaving moisture may cause unevenness. Soak a clean cloth in separately sold "ULTRA LIQUID" and apply it to the entire countertop. Allow "ULTRA LIQUID" to penetrate for about 5 minutes. However, if the applied amount is small and begins to dry, wipe it off before it dries. Once dried, it becomes difficult to wipe off, leading to uneven application. Using a new cloth, wipe the entire surface with "ULTRA LIQUID". If scratches are still noticeable, repeat steps 4-6. After application, it will dry in about 1 hour, but avoid contact with water for approximately 24 hours. 		

YOSHIMOTO SANGYO

Business hours: 9:00~17:30, Monday to Friday (except Japanese public holiday)

Tokyo Sales Office · LABO Headquarter • R&D • LABO 1-13-8, Imagome, Higashi-Osaka Hanai Building 7F, 1-2-9, Shiba City, Osaka, Japan Park, Minato-ku, Tokyo, Japan TEL: 072 967 2001 TEL: 03 3434 1700 FAX: 072 967 2003 FAX:03 3434 1710

